

MSD of New Durham Township Westville Schools

2017 Facility Assessment Report Overview

April 10, 2017









TERRY W. THORNSBURY, AIA

LEED®-AP BD+C
PRESIDENT, VIRIDIAN ARCHITECTURAL DESIGN, INC.
14 Year Veteran of U.S. Air Force
(Served in Desert Storm, Operation Enduring Freedom, Iraqi Freedom)









INTRODUCTION

During the fall and winter of 2016/2017, Viridian Architectural Design, Inc. was tasked with examining the existing building envelope, parking lots, hardscapes, playgrounds, interior, mechanical, electrical and plumbing systems for all the MSD of New Durham Township Westville Schools facilities. The following documents are the observations and recommendations from multiple site visits and examinations of each section of the building. As noted, a few of the existing systems have exceeded their typical life expectancy. There are quite a few existing systems still in fair to good condition. The probable costs of the recommended systems replacement, as outlined at the end of this report, are based upon Winter 2016 pricing. (Please note that this pricing excludes any additional contingency funds for unforeseen issues during the construction and systems replacement process.)







SYMBOLS

Building Conditions:

Fair

Poor

Failed

Good Building Condition - A building system that may last another fifteen (15) plus years with fair maintenance practices.

Fair Building Condition -A building system that may last another five to seven (5-7) years with good maintenance practices.

Poor Building Condition - A building system that needs immediate maintenance attention and may be harming the surrounding building systems. Poor building systems need to be replaced within the next two (2) years.

Failed Building Condition - A failed building system may be potentially harming the surrounding building systems. Failed building systems need immediate maintenance attention and need to be replaced as soon as possible.








CAMPUS



Aerial View

BUILDING










ASSESSMENT SHEET EXAMPLE









PRESCHOOL







RESTROOM

Restroom Data		
Location:	Restroom #1	
Fixtures:	Good	
Flooring:	Fair	
Walls:	Fair	
Ceiling:	Fair	
Doors:	Good	
Accessories:	Good	
Overall Condition:	Fair	
Replacement Cost:	\$15,000 - \$20,000	
Gene	General Notes:	
Restrooms do not meet current ADA requirements.		

Image Legend:

- 1. Wear and tear on existing flooring system.
- 2. No vertical grab bar per ADA requirements.
- 3. No horizontal grab bar per ADA requirements.
- 4. No turn / maneuvering space per ADA requirement.
- 5. Pipe covers do not cover entire pipe.







RESTROOM











PARKING AND HARDSCAPES

Parking and Hardscapes		
Location:	Back of Main Building	
Sidewalk Material:	Concrete	
Sidewalk Condition:	Failed	
Replacement Cost:	\$5,000	
Gene	General Notes:	
Replace damaged stoop in its entirety.		

Image Legend:

1. Some concrete step / stoop damage due to freeze / thaw.







PARKING AND HARDSCAPES











EXTERIOR CAMPUS BUILDING ENVELOPE







EXTERIOR DOORS

Exterior Door System Data	
Door Designation:	#1 Exterior
Door Material:	Hollow Metal
Weather Stripping:	Poor
Door Closers:	Good
Door Glazing:	Insulated 1" & 1/2"
Sidelites/Transoms:	Poor
Vestibule:	Yes
Overall Condition:	Poor
Replacement Cost:	\$16,500
General Notes:	
Recommended to inspect, maintain, and clean door	
system regularly to prolong life expectancy. Door	
does not have electronic security.	

Image Legend:	
1. Door rusting.	
2. Newer hardware.	
3. Some weather stripping missing.	
4. Sweeps worn out.	
5. Excessive wear / abuse.	
6. No ADA push buttons.	








EXTERIOR DOORS

Location: #1 Exterior












EXTERIOR DOORS

Location: #1 Exterior











MASONRY / SEALANT

Masonry / Sealant Data (Con.)	
Masonry:	Good
Cladding:	Poor
Flashing / Trim:	Poor
Caulking / Sealant:	Fair
Overall Condition:	Failed
Replacement Cost:	\$125,000 - \$150,000
General Notes:	
Recommend replacing trim to ensure water sheds away from building to prevent water issues in the future	

Image Legend:

- 1. Trim Slopes back towards building
- 2. Transition between window and facade trim not aligned causing water issues.







MASONRY / SEALANT











INTERIOR CAMPUS CONDITIONS







CORRIDORS

Corridor Data		
Category:	Floors	
Flooring Type:	Terrazzo	
Flooring Condition:	Poor	
Wall Base Type:	Rubber	
Wall Base Condition:	Fair	
Accessories:	Good	
Overall Condition:	Poor	
Replacement Cost:	\$90,000 - \$140,000*	
General Notes:		
General condition of corridor flooring is poor. The floor is cracking and needs repaired / replaced. *(Estimate of repair cost based on \$2-\$3/SF)		

Image Legend:

- 1. Floor surface is cracking in many places.
- 2. Flooring surface is damaged.
- 3. Threshold in corridor. Some floor mounted door stops in corridor are trip hazards.
- 4. Floor tile gap developing.







CORRIDORS











CORRIDORS

Corridor Data	
Category:	Ceiling (Con.)
Ceiling Type:	Drop - ACT
Panel Condition:	Poor
Grid / Accessories:	Good
Overall Condition:	Fair
Replacement Cost:	\$90,000 - \$145,000*
General Notes:	
Various ceiling tiles need to be replaced. Sources of	
water damage need to be identified and repaired.	
Panels are overall rated as 'Poor' due to many	
instances of damage/stains.	

instances of damage/stains.

*(Cost basis: \$4.50/SF)

Image Legend:

- 1. Various ceiling tiles have water stains.
- 2. Various ceiling tiles are physically damaged.
- 3. Some ceiling tiles are loose due to damage or warping.







CORRIDORS











MAINTENANCE / STORAGE

Maintenance & Storage Data		
Location:	Maintenance & Storage	
Floor Material:	Concrete	
Wall:	CMU Block	
Storage Conditions:	Poor	
Lighting:	Poor	
Overall Condition:	Poor	
Replacement Cost:		
General Notes:		
Storage room has major	Storage room has major drainage issues.	

Image Legend:

- 1. Drainage issues in space
- 2. Walls need painted.
- 3. Abestos on present on pipes in tunnels







MAINTENANCE / STORAGE











RESTROOMS

Restroom Data		
Location:	Men	
Fixtures:	Fair	
Flooring:	Fair	
Walls:	Fair	
Ceiling:	Good	
Accessories:	Good	
Overall Condition:	Fair	
Replacement Cost:	\$60,000 - \$75,000	
Gene	General Notes:	
Condition of finishes is fair to good. However, the		
restroom layout is not ADA compliant.		

Image Legend:

- 1. Flooring is damaged / deteriorated.
- 1. Mirror installed above height required for ADA.
- 2. Pipe cover does not meet current ADA access requirements.
- 4. No ADA stalls / urinals.







RESTROOMS











ELEMENTARY







ELEMENTARY CLASSROOMS

Classroom Data		
Category:	Flooring	
Туре:	VCT & Carpet	
Category:	Wall Base	
Туре:	Rubber	
Overall Condition:	Fair	
Replacement Cost:	\$115,000 - \$176,000*	
General Notes:		
The elementary school classroom flooring is in fair		
condition.		
*(Cost basis for all classrooms)		

Image Legend:

- 1. Carpet is showing signs of aging and wear.
- 2. Carpet is wrinkling, which poses a tripping hazard.
- 3. VCT is showing signs of aging and wear.







ELEMENTARY CLASSROOMS











MIDDLE SCHOOL







MIDDLE SCHOOL CLASSROOMS

Classroom Data		
Category:	Casework	
Type:	Lower	
Countertop:	Laminate	
Casework Material:	Laminate and Wood	
Overall Condition:	Poor	
Туре:	Full Height Cabinet	
Casework Material:	Laminate and Wood	
Overall Condition:	Fair	
Replacement Cost:	\$125,000 - \$140,000	
Gene	General Notes:	
Overall condition of casework is poor and needs replaced.		

Image Legend	ľ
--------------	---


- 1. Laminate is peeling off.
- 2. Countertop edges are worn.







MIDDLE SCHOOL CLASSROOMS











HIGH SCHOOL







HIGH SCHOOL CLASSROOMS

Classroom Data		
Category:	Wall Surfaces	
Туре:	Painted Drywall	
Overall Condition:	Fair	
Туре:	Painted CMU	
Overall Condition:	Fair	
Туре:	Trim	
Overall Condition:	Fair	
Туре:	White/Tack Boards Etc	
Overall Condition:	Fair	
Replacement Cost:	\$1,500 - \$2,500/per room	
General Notes:		

Wall surfaces in HS classrooms (typ Rm 15 - 24) need spot repairs and in some cases more extensive refinishing. Wall damage from removal of adhesive (tape etc) is evident. Suggest more durable surfaces and paints and use of removable hanging products.

Image Legend:

- 1. Typical spot repairs of wall surface and paint are needed.
- 2. Typical example of equipment removal where wall (and ceiling) were not repaired.
- 3. More extensive example of uncompleted wall repair after equipment reconfiguration.







MECHANICAL, ELECTRICAL, PLUMBING (MEP)







CAMPUS MECHANICAL

Media Center Air Handler	
Tag	AHU-4
Type:	Modular Air Handler
Zone Control:	Variable air volume boxes with hot water reheat
Installation Date:	2000
Controls:	DDC
Overall Condition:	Good
Pumps:	Inline cooling pump
Controls:	DDC
Overall Condition:	V 100000000
Replacement Cost:	\$140,000-\$165,000
General Notes:	
AHU-4 is a cooling only variable air volume air handler	

AHU-4 is a cooling only variable air volume air handler that serves the media center. Heating is provided at the VAV box hot water coils.

Image Legend:

- 1. AHU-4
- 2. AHU-4 chilled water pump.







CAMPUS MECHANICAL











CAMPUS ELECTRICAL

Building Lighting Data		
Elementary School		
Fluorescent Fixtures		
Wall Switches		
2000-2001		
4 years		
Poor		
\$150,000 - \$160,000		
General Notes:		

Current lighting system is inefficient and aged, several lamps are out, and lenses are dingy. Light levels in many areas are dim. Upgrade to newer LED light fixtures is needed. Occupancy sensor controls

should also be installed in most areas for energy savings.

Image Legend:

1. Elementary classroom showing dim lighting and aged light fixtures.







CAMPUS ELECTRICAL















ROOF SYSTEMS

Existing Roof Data					
Roof Section Number:	2				
Roof Area:	27,626 SF				
Year Installed:					
Warranty Period:					
Roof Composition:	Single Ply-EPDM over Rigid Polyisocyanurate				
Core Sample:	Not Available				
Overall Roof Condition:	Poor				
Visible Defects:	1 -Sealant issues.2 -Ponding around drains.3 -Ponding near gutters.4. General maintenance.				
Recommendations:	Roof replacement.				
Cost of Repairs:	See probable cost section.				

Image Legend:

- 1. Internal ponding, not sloping properly to drains or gutter. High points not allowing water to flow through.
- 2. No coping on top of wall.
- 3. Lip at gutter edge prevents flow of water to drain.
- 4. Mechanical penetrations to have crickets to drain water away from their curbs.


General Note: Roof membrane overall is in fair condition, but lack of drainage at gutters, equipment curbs lack of coping and general bad maintenance may create serious issues soon!

















Existing Roof Data			
Roof Section Number:	20		
Roof Area:	2,538 SF		
Year Installed:			
Warranty Period:			
Roof Rating:	Failed		
Roof Composition:	Asphalt Shingle		
Core Sample:	Not Available		
Overall Roof Condition:	Failed		
Visible Defects:	1 - Shingle old, deteriorated.2. General maintenance.		
Recommendations:	Due to expansion of caffeteria, building indicated may be removed.		
Cost of Repairs:	See probable cost section.		

	Image Legend:
1. Shingles are old and deteriorated.	
2. General site condition has lack of drainage.	















EXTERIOR CAMPUS CONDITIONS







PARKING AND HARDSCAPES

Parking and Hardscapes				
Location:	See Key Plan			
Surfacing Material:	Asphalt			
Parking Condition:	Poor			
Drainage:	Poor			
Sidewalk Material:	Material: Concrete			
Sidewalk Condition:	Fair			
Pavement Cost:	\$500,000.00			
Drainage Cost:	\$1M-\$2M			
Sidewalk Cost:	\$250,000-\$750,000			
General Notes:				
Recommend to replace and repair sidewalk /				

asphalt that is damaged / deteriorated. Parking has
drainage issues that need to be addressed.

	Image	Legend
--	-------	--------

- 1. Shear cracks and missing concrete at sidewalks.
- 2. Parking lot showing signs of aging and cracking needs to be resurfaced.
- 3. Some sidewalk collapse due to drainage issues.
- 4. No inlet in parking lot.
- 5. Some concrete step / stoop damage due to freeze / thaw.







PARKING AND HARDSCAPES











PARKING AND HARDSCAPES











ATHLETIC FIELDS

Athletic Fields Data - Itemized			
Location: Baseball Field			
Category:			
Condition:			
Replacement Cost:	\$80,000 -\$100,000		
General Notes:			
Recommende paint, ma wood and walls to prolo	intain, and clean exposed ong life expectancy.		

Image Legend:


- 1. Block walls not painted.
- 2. Exposed wood shows signs of aging, paint is peeling off.







ATHLETIC FIELDS









PLAYGROUND

Playground Data (Con.)				
See Key Plan				
Wood chips / Mulch				
Metal / Plastic				
Fair				
\$75,000 - \$125,000				
\$150,000 -\$350,000				
General Notes:				

Image Legend:


- 1. Playground does not drain well.
- 2. Playground swing area needs rebuilt.








PLAYGROUND











FACILITY ASBESTOS REPORT







ASBESTOS

Westville Schools Asbestos Report				
Material	ACBM (Yes or Assumed	Quantity	Cost of Abatement (\$)	Units
Sprayed On Soft Plaster	Yes	790	9,480.00	SF
Floor Tile & Black Mastic	Yes	56,250	112,500.00	SF
Thermal System Boiler Pipe Insul.	Yes	500 - 700	12,000.00	LF
Exterior Transite Panels	Yes	1,500	7,500.00	SF
12" x 12" Brown & Cream Floor Tile	Yes	200	400.00	SF
Total Quantified Abatement Cost \$ 141,880.00				







PROBABLE COST ESTIMATE







OVERALL PROBABLE COST

Westville Schools Overall Probable Cost				
Repair Cost		Low		High
Corporation Buildings Good	\$	5,897,650	\$	7,523,000
Corporation Buildings Fair	\$	8,131,256		\$10,825,256
Corporation Buildings Poor	\$	4,078,800	\$	5,575,800
Corporation Buildings Failed	\$	44,000	\$	44,000
Corporation Roofs Good	\$	-	\$	-
Corporation Roofs Fair	\$	1,735,040	\$	1,735,040
Corporation Roofs Poor	\$	1,212,320	\$	1,212,320
Corporation Roofs Failed	\$	-	\$	=
Corporation Asbestos	\$	141,880	\$	141,880
Corporation Overall	\$	21,240,946	\$	27,057,296

Contingency Fees	10%	10%
A/E Design Fees	6.5%*	7.5%**

^{* 6.5%} Is based on no public bidding being involved in the project.





^{**7.5%} Is based on the inclusion of the public bidding process.



CAMPUS









SITE DRAINAGE











CAFETERIA / KITCHEN











EXTERIOR DOORS











THANK YOU!

QUESTIONS?



