

EXECUTIVE SUMMARIES

During the course of the inspection at the Bridge Street Maintenance Building, three (3) material types were sampled and analyzed for asbestos content. These samples represented materials that were previously assumed to be ACM and were sampled to determine the actual asbestos content of the material or were previously not identified during the initial inspection.

The following materials were sampled and analyzed for asbestos contents:

<u>Material</u>	<u>Location</u>	<u>Status</u>	<u>Result</u>
1. Air cell pipe insulation	Basement	previously assumed	60% Chrysotile
2. 9" x 9" floor tile	2nd floor office	newly identified	Negative
3. 9" x 9" floor tile mastic	2nd floor office	newly identified	10% Chrysotile

Additional ACM that was previously not identified but now has been identified and incorporated into the management plan is listed below. These materials were also assessed and given response actions and priority rankings.

1. 9" x 9" floor tile and mastic second floor office

During the course of the three-year reinspection, a total of two (2) areas were assessed differently from the original inspection. These areas represented areas where the condition of the ACM had changed or deteriorated. These areas include the following locations:

1. Basement storage areas and hallways air cell pipe insulation and elbows
2. Second floor office 9" x 9" ~~tile~~/Mastic

The 9" x 9" floor tile and mastic are newly identified and will be added to the O & M program.

In the basement area, materials that were once considered to be non-friable or in good condition were assessed as being damaged and, therefore, are recommended for abatement. The priority of abatement can be found on Reinspection Form 2.

A tentative start and completion date is also included in the last column of the Reinspection Form 2. The cost associated with the abatement of the ACBM noted as being damaged or significantly damaged is given in the following cost estimates. These line items are also prioritized.

ABATEMENT COST ESTIMATES

<u>Location</u>	<u>Response Action</u>	<u>ACBM Quantity</u>	<u>Estimated Contractor Cost</u>
1. Basement storage	4	450 LF	\$6,750

Consulting Fees

It is estimated that approximately \$2,400 will be required for project monitoring during removal. An additional consulting fee of approximately \$1,200 should be budgeted for AHERA required project design, associated contract administration, and project management.

It should be noted that only locations with assessments of 1 through 5 are recommended for abatement.

EPA CERTIFICATION REQUIREMENTS

The certificates of the individuals involved in conducting the inspections and preparing the management plan update are appended to this document.

School Waint Blvd, Old Post Office Building 1931 Date(s) of Original AHERA Inspection March 1-6, 90

Homogeneous sampling areas		Material category	Asbestos content	Friability	AHERA assessment category (1-7, X, None)	Recorded locations of material for each assessment category	Response actions taken/renovations/other comments
ID number	Material description						
A (1)	Boiler + associated plumbing insulation	<input checked="" type="radio"/> TSI Surf. Misc.	Assumed Yes <input checked="" type="radio"/> No	F NF <input checked="" type="radio"/> X	None	Boiler Room	None - ACB4
A (2)	Boiler Breaching (Flue) 125 SF	<input checked="" type="radio"/> TSI Surf. Misc.	Assumed Yes No	F NF X	7	Boiler Room	Removed?
A (3)	Aircell type pipe insulation 400 LF	<input checked="" type="radio"/> TSI Surf. Misc.	Assumed Yes No	F NF X	7	Basement storage areas and hallways	
A (3)	" SOLE	<input checked="" type="radio"/> TSI Surf. Misc.	Assumed Yes No	F NF X	1	"	
A (3)	Asbestos containing plaster fittings on Air-cell lines 57	<input checked="" type="radio"/> TSI Surf. Misc.	Assumed Yes No	F NF X	7	"	
A (3)	" 20	<input checked="" type="radio"/> TSI Surf. Misc.	Assumed Yes No	F NF X	1	"	

Information abstracted by Haine Vignone Date May 20, 93

Fraility: F = friable, NF = nonfriable, X = not applicable (material is non-ACBM)

AHERA assessment category: 1 = Damaged or significantly damaged TSI ACBM, 2 = Damaged friable surfacing ACBM, 3 = Significantly damaged friable surfacing ACBM, 4 = Damaged or significantly damaged friable miscellaneous ACBM, 5 = ACBM with potential for damage, 6 = ACBM with potential for significant damage, 7 = Any remaining friable ACBM or friable suspected ACBM, X = not applicable (material is non-ACBM or nonfriable surfacing or miscellaneous material), None = No assessment category provided in original inspection.

B-2

School Maint Bldg / Old Post Office Building 1931 Date(s) of Original AHERA Inspection March 1-8, '90

Homogeneous sampling areas		Material category	Asbestos content	Friability	AHERA assessment category (1-7, X None)	Recorded locations of material for each assessment category	Response actions taken/renovations/other comments
ID number	Material description						
B(1)	Wall + Ceiling Plaster 12,500 SF	TSI <input checked="" type="radio"/> Surf. <input type="radio"/> Misc.	Assumed Yes <input checked="" type="radio"/> No <input type="radio"/>	F <input checked="" type="radio"/> NF <input type="radio"/> X	None	Throughout Bldg	None - ACB 24
	<u>Newly Identified (1)</u> → 150 SF VHT Second Floor - Room above loading dock			F <input type="radio"/> NF <input type="radio"/> X			
		TSI <input type="radio"/> Surf. <input type="radio"/> Misc.	Assumed Yes <input type="radio"/> No <input type="radio"/>	F <input type="radio"/> NF <input type="radio"/> X			

Information abstracted by Alain Vlasse Date May 28 '93

Friability: F = friable, NF = nonfriable, X = not applicable (material is non-ACBM)
 AHERA assessment category: 1 = Damaged or significantly damaged TSI ACBM, 2 = Damaged friable surfacing ACBM, 3 = Significantly damaged friable surfacing ACBM, 4 = Damaged or significantly damaged friable miscellaneous ACBM, 5 = ACBM with potential for damage, 6 = ACBM with potential for significant damage, 7 = Any remaining friable ACBM or friable suspected ACBM, X = not applicable (material is non-ACBM or nonfriable surfacing or miscellaneous material), None = No assessment category provided in original inspection.

Sample Reinspection Form 2. Reinspection of ACBM: Findings and Management Planner Recommendations

School Maintenance Building Building 1931 Date(s) of Reinspection June 15, 1993

Homogeneous Sampling Area: Material Description Boiler Breathing ID Number A (2)

REINSPECTION FINDINGS FOR ACBM

Location(s) of ACBM by assessment category	Quantity	Fria-bility	Assess-ment cate-gory (1-7, X)	Justification of assessment category	Change in assess-ment	Preventive measures, response actions, and initial/additional cleanings	Schedule	
							Begin	Com-plete
Boiler Room	125 SF.	<input checked="" type="radio"/> E	7	Material is in good condition no cracks is extremely limited	Yes <input checked="" type="radio"/> No	7		
Boiler cover cracking		NF			Yes <input type="radio"/> No			
Breeding Cracking		F			Yes <input type="radio"/> No			
		NF			Yes <input type="radio"/> No			

Were additional samples of this ACBM collected? Yes No

Date of management planner review: _____

Inspector name Bob Merrier

Management planner name _____

Inspector signature _____

Management planner signature _____

Accreditation #/State _____

Accreditation #/State _____

Expiration date _____

Expiration date _____

I, the LEA's _____ ated Person, have read and understood the recommendations made above: _____ Date: _____

School Maintenance Building Building 1931

Date(s) of Reinspection June 15, 1993

Homogeneous Sampling Area: Material Description Air Cell Pipe Insulation on ceiling

ID Number A(3)

REINSPECTION FINDINGS FOR ACM

MANAGEMENT PLANNER RECOMMENDATIONS

Location(s) of ACM by assessment category	Quantity	Friability	Assessment category (1-7, X)	Justification of assessment category	Change in assessment	Preventive measures, response actions, and initial/additional cleanings	Schedule	
							Begin	Complete
Air Cell pipe insulation and elbows in Basement	450LF including elbows	<input checked="" type="checkbox"/> NF	7	Some exposed ends and a couple of damaged elbows but building is unoccupied and basement isn't used.	<input checked="" type="checkbox"/> No	4		
Air Cell pipe insulation and Elbows First Floor	30LF including elbows	<input checked="" type="checkbox"/> NF	7	Material is in fair condition but building is unoccupied (Additional material not shown on W.P.P.)	<input checked="" type="checkbox"/> No	Add to O.M. plan.		

Were additional samples of this ACM collected? Yes No Positive Gorb's Crystallite

Date of management planner review: _____

Inspector name Bob Mercer

Management planner name _____

Inspector signature _____

Management planner signature _____

Accreditation #/State _____

Accreditation #/State _____

Expiration date _____

Expiration date _____

I, the LEA's _____, dated Person, have read and understood the recommendations made above: _____ Date: _____

Sample Reinspection Form 2. Reinspection of ACBM: Findings and Management Planner Recommendations.

School Maintenance Building Building 1931

Date(s) of Reinspection June 15, 1993

Homogeneous Sampling Area: Material Description 9' x 9' VAT

ID Number C(1) Newly Identified

REINSPECTION FINDINGS FOR ACBM

Location(s) of ACBM by assessment category	Quantity	Friability	Assessment category (1-7, X)	Justification of assessment category	Change in assessment	Preventive measures, response actions, and initial/additional cleanings	Schedule	
							Begin	Complete
2nd Floor Office	150sf.	F	X	Material is in Fair Condition on building is unrecorded.	No	Add to O.M. plan		
		F			Yes			
		NF			No			

Were additional samples of this ACBM collected? Yes No Title is Negative (Plastic is Positive)

Date of management planner review: _____

Inspector name Bob Mercier

Management planner name _____

Inspector signature _____

Management planner signature _____

Accreditation #/State _____

Accreditation #/State _____

Expiration date _____

Expiration date _____

I, the LEA's _____, dated Person, have read and understood the recommendations made above: _____ Date: _____

EnviroScience Consultants inc.

Environmental Engineering • Industrial Hygiene • Laboratory Services

**SAMPLE LOG
ASBESTOS BULKS**

PLM

PROJECT NAME: New Milford Altera - School Maint Bld - Bridge St PROJECT # 90-02341

SAMPLE ID#	BUILDING & LOCATION	MATERIAL TYPE	RESULT (%)
6-15-Bm-26	Maint Bld. 2nd Floor	9x9 Tile	None
-27	2nd Floor	4x9 Tile	None
-28	↓	9x9 Tile	None.
-29		mastic	not sent
-30		mastic	not sent
31		mastic	not sent.
32	Basement	TSI pipe insulation	60%
33	↓	pipe insulation	N.A.
34	↓	elbow	N.A.

TEST METHOD: PLM TURNAROUND TIME: Routine

Based on turnaround time indicated above, it is ESC's belief that results are due on or before this date: 7-17. Please call if sample results are going to be late.

FAX RESULTS TO: Marsha Monroe

SPECIAL INSTRUCTIONS: Stop on first positive in the following
sets of three (26,27,28) (32,33,34) do not analyze
sample no. (29,30,31)

SAMPLES COLLECTED BY: Bob Mercer DATE: 6-15-93 TIME: pm

SAMPLES SENT BY: MJ Monroe DATE: 7-7-93 TIME: _____

SAMPLES RECEIVED BY: _____ DATE: _____ TIME: _____

SHIPPED TO: _____ EMSL (State _____) _____ EMSL A _____ OTHER: Hygeia

SHOULD ESC'S CLIENT BE CALLED WITH VERBALS? Yes No

METHOD OF SHIPMENT: UPS - Reg. UPS Overnite Fed Ex Other: _____

SMPLOG:PC6