

Executive Summary

During the course of the inspection at the Lillis Administration Building, one (1) material type was sampled and analyzed for asbestos content. The sample represented material that was previously assumed to be ACM and was sampled to determine the actual asbestos content of the material.

The only samples taken in the Lillis Administration Building were of 9" x 9" floor tile. The results indicated 2% chrysotile asbestos in the tile.


No additional ACM was identified.

During the course of the three-year reinspection, there were no areas assessed differently from the original inspection.

There are not immediate abatement activities recommended for this building.

EPA CERTIFICATION REQUIREMENTS

The certificates of the individuals involved in conducting the inspections and preparing the management plan update are appended to this document.



Sample Reinspection Form 1. Original AHERA Inspection Information Abstracted from the Management Plan

School Willis Adams Bldg Building 1931 Date(s) of Original AHERA Inspection MARCH 1-6, 90

Homogeneous sampling areas		Material category	Asbestos content	AHERA assessment category (1-7, X, None)	Recorded locations of material for each assessment category	Response actions taken/renovations/other comments
ID number	Material description					
A (1)	Thermal System Insulation	TSI Surf. Misc.	Assumed Yes	7	Vertical/False-wall chases	
B (1)	Ceiling plaster	TSI Surf. Misc.	Assumed Yes	None	N/A	NOV-ACBM
C (1)	1'x1' cellulose- type ceiling tiles	TSI Surf. Misc.	Assumed Yes	None	N/A	NOV-ACBM
C (2)	9" x 9" Plyer tile 5800 SF	TSI Surf. Misc.	Assumed Yes	X	throughout School	↑
		TSI Surf. Misc.	Assumed Yes			
		TSI Surf. Misc.	Assumed Yes			

Information abstracted by Alaine Wagner Date May 28, 93

Friability: F = friable, NF = nonfriable, X = not applicable (material is non-ACBM)  
 AHERA assessment category: 1 = Damaged or significantly damaged TSI ACBM, 2 = Damaged friable surfacing ACBM, 3 = Significantly damaged friable surfacing ACBM, 4 = Damaged or significantly damaged friable miscellaneous ACBM, 5 = ACBM with potential for damage, 6 = ACBM with potential for significant damage, 7 = Any remaining friable ACBM or friable suspected ACBM, X = not applicable (material is non-ACBM or nonfriable surfacing or miscellaneous material), None = No assessment category provided in original inspection.

Sample Reinspection Form 2. Reinspection of ACBM: Findings and Management Planner Recommendations

School Lillis Administration Building Building 1931 Date(s) of Reinspection June 15, 1993  
 Homogeneous Sampling Area: Material Description Thermal System Insulation ID Number ALI

REINSPECTION FINDINGS FOR ACBM

Location(s) of ACBM by assessment category	Quantity	Fia-bility	Assessment category (1-7, X)	Justification of assessment category	Change in assessment	MANAGEMENT PLANNER RECOMMENDATIONS	
						Preventive measures, response actions, and initial/additional cleanings	Schedule
						Begin	Complete
Vertical Wall Chases (assumed to exist)	?	(E) NF	7	Material cannot be assessed unless chases are demolished	Yes (NO)	7	
		F			Yes		
		NF			No		

Were additional samples of this ACBM collected? Yes  No

Date of management planner review: \_\_\_\_\_

Inspector name Bob Mercier

Management planner name \_\_\_\_\_

Inspector signature \_\_\_\_\_

Management planner signature \_\_\_\_\_

Accreditation #/State \_\_\_\_\_

Accreditation #/State \_\_\_\_\_

Expiration date \_\_\_\_\_

Expiration date \_\_\_\_\_

I, the LEA's \_\_\_\_\_ dated Person, have read and understood the recommendations made above: \_\_\_\_\_ Date: \_\_\_\_\_

School Lillis Administration Building Building 1931 Date(s) of Reinspection June 15, 1993

Homogeneous Sampling Area: Material Description 9x9 Floor tile ID Number C(2)

REINSPECTION FINDINGS FOR ACBM

MANAGEMENT PLANNER RECOMMENDATIONS

Location(s) of ACBM by assessment category	Quantity	Findability	Assessment category (1-7, X)	Justification of assessment category	Change in assessment	Preventive measures, response actions, and initial/additional cleanings	Schedule	
							Begin	Complete
Through out building	5800 SF	F	X	Material is in good condition 2 classrooms have been covered with new 12"x12" VCT est. 1800 SF.	Yes	7		
<i>Van 2 office moved</i>		F			Yes			
<i>Handlery dist</i>		NF			No			
<i>Handlery dist</i>		NF			No			

Were additional samples of this ACBM collected?  Yes  No Positive (2% Chrysothle)

Date of management planner review: \_\_\_\_\_

Inspector name Bob Mercier

Management planner name \_\_\_\_\_

Inspector signature \_\_\_\_\_

Management planner signature \_\_\_\_\_

Accreditation #/State \_\_\_\_\_

Accreditation #/State \_\_\_\_\_

Expiration date \_\_\_\_\_

Expiration date \_\_\_\_\_

I, the LEA's \_\_\_\_\_ dated Person, have read and understood the recommendations made above: \_\_\_\_\_ Date: \_\_\_\_\_