

EXECUTIVE SUMMARIES

During the course of the inspection at the Northville Elementary School, two (2) material types were sampled and analyzed for asbestos content. These samples represented materials that were previously assumed to be ACBM and were sampled to determine the actual asbestos content of the material.

No additional ACBM was identified.

The following materials were sampled and analyzed for asbestos content:

<u>Material</u>	<u>Location</u>	<u>Status</u>	<u>Result</u>
1. Boiler Breeching/ Flue Cement	Boiler Room	Previously assumed	Negative
2. 12" x 12" floor tile	Throughout	Previously assumed	Negative
3. 12" x 12" floor tile mastic	Throughout	Previously assumed	15% Chrysotile

During the course of the three-year reinspection, no areas were assessed differently from the original inspection.

Currently there are no abatement response actions recommended for this building.

EPA CERTIFICATION REQUIREMENTS

The certificates of the individuals involved in conducting the inspections and preparing the management plan update are appended to this document.

*Laboratory  
Office + CRIS carpeted  
Hallways 12x12 tiled - good condition  
+ cafe*

School Northville Elementary Building 1981-82 Date(s) of Original AHERA Inspection March 1-6, 90

Homogeneous sampling areas		Material category	Asbestos content	Friability	AHERA assessment category (1-7, X=None)	Recorded locations of material for each assessment category	Response actions taken/renovations/other comments
ID number	Material description						
A (1)	Plumbing and Fluor Breaching 300 SF	<input checked="" type="radio"/> TSI Surf. Misc.	<input checked="" type="radio"/> Assumed Yes No	<input checked="" type="radio"/> F NF X	7	Boiler Room	Material was encapsulated Material is in good condition Apr. 2008
A (1)	Elbows/Fittings on FG lines not quantified	<input checked="" type="radio"/> TSI Surf. Misc.	<input checked="" type="radio"/> Assumed Yes No	<input checked="" type="radio"/> F NF X	7	Boiler Room	There is no such thing as management plan
C (1)	2 1/4" Layer-in Ceiling tile 47,040 SF	<input checked="" type="radio"/> TSI Surf. Misc.	Assumed Yes <input checked="" type="radio"/> No	F NF <input checked="" type="radio"/> X	None	"In the bldg"	Non-ACBM
C (2)	Wall covering textured 2,100 SF	<input checked="" type="radio"/> TSI Surf. Misc.	Assumed Yes <input checked="" type="radio"/> No	F NF <input checked="" type="radio"/> X	None	Hobbyist's Gymnasium Library	Non-ACBM
C (3)	Textured Panel Material cloth/resin exterior	<input checked="" type="radio"/> TSI Surf. Misc.	Assumed Yes <input checked="" type="radio"/> No	F NF <input checked="" type="radio"/> X	None	Exits	Non-ACBM
C (4)	12"x12" floor tile 9,725 SF	<input checked="" type="radio"/> TSI Surf. Misc.	<input checked="" type="radio"/> Assumed Yes No	F NF <input checked="" type="radio"/> X	X	Throughout the bldg	

Information abstracted by Alain Weisse Date May 28, 93

Friability: F = friable, NF = nonfriable, X = not applicable (material is non-ACBM)  
 AHERA assessment category: 1 = Damaged or significantly damaged TSI ACBM, 2 = Damaged friable surfacing ACBM, 3 = Significantly damaged friable surfacing ACBM, 4 = Damaged or significantly damaged friable miscellaneous ACBM, 5 = ACBM with potential for damage, 6 = ACBM with potential for significant damage, 7 = Any remaining friable ACBM or friable suspected ACBM, X = not applicable (material is non-ACBM or nonfriable surfacing or miscellaneous material), None = No assessment category provided in original inspection.

Sample Reinspection Form 2: Reinspection of ACBM: Findings and Management Planner Recommendations

School Northville Elementary Building 1231-82  
 Homogeneous Sampling Area: Material Description Boiler Replacing / Chloroform

Date(s) of Reinspection June 15, 1993  
 ID Number A(11)

REINSPECTION FINDINGS FOR ACBM					MANAGEMENT PLANNER RECOMMENDATIONS			
Location(s) of ACBM by assessment category	Quantity	Findability (1-7, X)	Assessment category (1-7, X)	Justification of assessment category	Change in assessment	Preventive measures, response actions, and initial/additional cleanings	Schedule	
							Begin	Complete
Boiler Room	300cf	F	7	Material is in good condition and is not accessible to students	Yes	Remove from O & M plan		
		NF			No			
		F			Yes			
		NF			No			

Were additional samples of this ACBM collected?  Yes  No (Negative)

Inspector name Bob Mercier  
 Inspector signature \_\_\_\_\_  
 Accreditation #/State \_\_\_\_\_  
 Expiration date \_\_\_\_\_

Date of management planner review: 6.6.93  
 Management planner name \_\_\_\_\_  
 Management planner signature \_\_\_\_\_  
 Accreditation #/State 93-546-136-108/CT  
 Expiration date 6.14.94

I, the LEA's \_\_\_\_\_, dated Person, have read and understood the recommendations made above: \_\_\_\_\_ Date: \_\_\_\_\_

Sample Reinspection Form 2. Reinspection of ACBM: Findings and Management Planner Recommendations

School Northville Elementary Building 1001-01 Date(s) of Reinspection June 15, 1993  
 Homogeneous Sampling Area: Material Description 12" x 12" Floor Tile ID Number 2(A)

REINSPECTION FINDINGS FOR ACBM

Location(s) of ACBM by assessment category	Quantity	Fita-bility	Assess-ment category (1-7, X)	Justification of assessment category	Change in assess-ment	Preventive measures, response actions, and initial/additional cleanings	Schedule	
							Begin	Com-plete
<u>Thoroughout School</u>	<u>9,725 SF.</u>	<u>F</u>	<u>X</u>	<u>Some areas have been covered with carpeting or new 12x12 tile</u>	<u>Yes</u>	<u>7</u>		
		<u>F</u>			<u>Yes</u>			
		<u>NF</u>			<u>No</u>			
		<u>NF</u>			<u>No</u>			

Were additional samples of this ACBM collected?  Yes  No Tile is negative (Positive Mastic)

Inspector name Bob Mercer

Inspector signature \_\_\_\_\_

Accreditation #/State \_\_\_\_\_

Expiration date \_\_\_\_\_

MANAGEMENT PLANNER RECOMMENDATIONS

Date of management planner review: \_\_\_\_\_

Management planner RAYMOND R. FOLLINO

Management planner signature \_\_\_\_\_

Accreditation #/State \_\_\_\_\_

Expiration date \_\_\_\_\_

I, the LEA's \_\_\_\_\_, dated Person, have read and understood the recommendations made above: \_\_\_\_\_ Date: \_\_\_\_\_

HYGEIA PROSCIENCE SUMMARY SHEET  
Hygeia ProScience Client No. 80096  
EnviroScience Consultants, Inc.

July 28, 1993

Client Reference: Project No. 00-0234D, Northville School

06-15-BM-08, Cafe, Mastic

Asbestos 15% (Chrysotile); Non-Fibrous Material 85%; (Black)

Date of Collection: 6/15/93

Analysis Date: 7/27/93 Analyst: M. Manning

06-15-BM-09, Entry Door, 12 x 12 Brown Floor Tile

No Asbestos Detected, Non-Fibrous Material 100%; (Brown)

Date of Collection: 6/15/93

Analysis Date: 7/14/93 Analyst: M. Manning

06-15-BM-10

Did not analyze

06-15-BM-11, Entry Hall, 12 x 12 Brown Floor Tile

No Asbestos Detected, Non-Fibrous Material 100%; (Brown)

Date of Collection: 6/15/93

Analysis Date: 7/14/93 Analyst: M. Manning

06-15-BM-12

Did not analyze

# EnviroScience Consultants Inc.

Environmental Engineering • Industrial Hygiene • Laboratory Services

SAMPLE LOG  
ASBESTOS BULKS

PLM pg 1 of 2

PROJECT NAME: New Milford AHERN Reinspection - Northville Sch. PROJECT # 90-0234D

SAMPLE ID#	BUILDING & LOCATION	MATERIAL TYPE	RESULT ( % )
G-15-BM-01	Northville Boiler Rm	Flue cement	
02	Boiler Rm	↓	
03	↓	↓	
04	↓	Breeching	
05	↓	↓	
06	↓	↓	
07	Cafe	12x12 Tile (Red)	
08	Cafe	mastic	
09	Entry Door	12x12 Tile (Brown)	
10	Entry Door	mastic	

TEST METHOD: PLM TURNAROUND TIME: Routine

Based on turnaround time indicated above, it is ESC's belief that results are due on or before this date: 7-13. Please call if sample results are going to be late.

FAX RESULTS TO: Marsha Monroe

SPECIAL INSTRUCTIONS: Slap analysis on first positive in the following sets of samples (01,02,03) (04,05,06) (07,09,11) do not analyze sample no. (08,10,12)

SAMPLES COLLECTED BY: Bob Mercer DATE: 6-15-93 TIME: pm

SAMPLES SENT BY: M Monroe DATE: 7-7-93 TIME: \_\_\_\_\_

SAMPLES RECEIVED BY: \_\_\_\_\_ DATE: \_\_\_\_\_ TIME: \_\_\_\_\_

SHIPPED TO: \_\_\_\_\_ EMSL (State \_\_\_\_\_) \_\_\_\_\_ EMSL A \_\_\_\_\_ OTHER: Hygeil

SHOULD ESC'S CLIENT BE CALLED WITH VERBALS?  Yes  No

METHOD OF SHIPMENT:  UPS - Reg.  UPS Overnite  Fed Ex  Other: \_\_\_\_\_

SMPLOG:PC6

